

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404162276

Date Received:
04/11/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: <u>10690</u>	Contact Name and Telephone:	
Name of Operator: <u>IMPETRO RESOURCES LLC</u>	Name: _____	
Address: <u>558 CASTLE PINES PKWY UNIT B-4</u>	Phone: () _____	Fax: () _____
City: <u>CASTLE PINES</u> State: <u>CO</u> Zip: <u>80108</u>	Email: _____	

Additional Operator Contact:

Contact Name	Phone	Email
<u>Bongers, Brent</u>	<u>361-935-5633</u>	<u>bbongers@impetroresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718700275

Inspection Date: 04/07/2025 FIR Submit Date: 04/10/2025 FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 317278

Location Name: CHANDLER-62N49W Number: 15NWNE County: _____

Qtrqtr: NWNE Sec: 15 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.145840 Longitude: -102.840590

FACILITY - API Number: 05-121-00 Facility ID: 317278

Facility Name: CHANDLER-62N49W Number: 15NWNE

Qtrqtr: NWNE Sec: 15 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.145840 Longitude: -102.840590

CORRECTIVE ACTIONS:

1	CA# <u>203969</u>	
Corrective Action:	<u>Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.</u>	Date: <u>04/24/2025</u>
Response:	<u>CA COMPLETED</u>	Date of Completion: <u>04/11/2025</u>
Operator Comment:	<u>Additional maintenance has been conducted along the south side of location on the berms and pit walls and well location.</u>	
ECMC Decision:	_____	

ECMC
Representative:

2 CA# 203970

Corrective Action: Remove produced liquid hydrocarbons from the earthen pit or reservoir immediately per Rule 909.d.

Date: 04/12/2025

Response: CA COMPLETED

Date of Completion: 04/11/2025

Operator
Comment:

Hydrocarbon sheen and algae on surface of the skim pit has been removed with vac truck.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 4/11/2025 2:59:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404162312	Photolog
-----------	----------

Total Attach: 1 Files