

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 389 From entrance to location




Photo # 390 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 391 Location



Photo # 392 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 393 Location




Photo # 394 Hog panel laying on the ground/debris

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



**Photo # 395 Bird protection damaged & needs maintenance
/wildlife hazard**



**Photo # 396 Bird protection damaged & needs maintenance
/wildlife hazard**

