

Interim Reclamation and Stormwater Inspection

April 9, 2025

Operator: TYLER ROCKIES EXPLORATION LTD - 41550

Location ID: 320628

Well Name: PEORIA J-SAND UNIT #36

Inspection Document #: 718600474

Arapahoe County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PEORIA J-SAND UNIT #36
Location ID: 320628



Photo 1. Overview of well location looking east.



Photo 2. Looking south down west side of location. There is some desirable vegetation on the west side of location.



Inspection Photos
Location Name: PEORIA J-SAND UNIT #36
Location ID: 320628



Photo 3. Looking north along the west side of location. List B noxious weed Scotch Thistle is present around the perimeter of location.



Photo 4. Looking south along the east side of location. List B noxious weed Scotch Thistle is present on this side (red circle). Vehicle tracks appear to be using the east side of pad as a turn around area.



Inspection Photos
Location Name: PEORIA J-SAND UNIT #36
Location ID: 320628



Photo 5. Looking east from the east side of the pad. This area is primarily bare sand/ gravel and appears to have vehicle tracks on it. There appears to be sediment leaving the location by erosion (red circle). The east side of the location should be reclaimed and stabilized according to Rule 1003 standards.



Photo 6. Wellhead appears to be leaking and stained soil is present around the base.



Inspection Photos
Location Name: PEORIA J-SAND UNIT #36
Location ID: 320628



Photo 7. On the east side of location. An unmarked barrel. Secondary containment does not have wildlife exclusion device.



Photo 8. Barrels on the west side of location. Secondary containment does not have wildlife exclusion devices.



Inspection Photos
Location Name: PEORIA J-SAND UNIT #36
Location ID: 320628



Photo 9. Reference vegetation to the west of well location.

