

Interim Reclamation and Stormwater Inspection

April 11, 2025

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 464908

Well Name: YELLOWSTONE/1-2

Inspection Document #: 718600485

Lincoln County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: YELLOWSTONE/1-2
Location ID: 464908



Photo 1. Looking north across the tank battery location. It appears that desirable vegetation is present on the interim areas. The location is mowed.



Photo 2. Looking west along the south side of location. See photo 1 comments.



Inspection Photos
Location Name: YELLOWSTONE/1-2
Location ID: 464908



Photo 3. Stained soil beneath valve on the east side of southern tank.



Photo 4. Looking north along the west side of the location. Desirable vegetation is present and mowed.



Inspection Photos
Location Name: YELLOWSTONE/1-2
Location ID: 464908



Photo 5. Stained soil around valve on the west side of the southernmost tank.



Photo 6. Separator shed.



Inspection Photos
Location Name: YELLOWSTONE/1-2
Location ID: 464908



Photo 7. Looking west down the north side of location. Desirable vegetation has established.



Photo 8. Picture taken on the east side of the northern fiberglass tank. Stained soil beneath valve.

