

# Inspection Photos

ID: 321591

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 4/9/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the location. There was a contractor onsite spreading manure. It was unknown if manure had been composted.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 4/9/2025

## Inspection Photos



**Photo 2.** Standing further back facing southeast.

