

# Inspection Photos

API: 017-07386

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 4/9/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone arial photo facing west toward the offsite tank battery location.



## Inspection Photos



**Photo 2.** Drone aerial photo facing west toward the abandoned wellsite.



## Inspection Photos



**Photo 3.** Facing west at the east side of the location former tank battery site. This area needs to be reclaimed and revegetated.



## Inspection Photos



**Photo 4.** Facing south at the east side of the location former tank battery site. This area needs to be reclaimed and revegetated.



## Inspection Photos



**Photo 5.** There is a small amount of gravel pile remains adjacent to the road that needs to be graded back on the road.



## Inspection Photos



**Photo 6.** Facing south at the abandoned wellsite location to the west shown in drone photo #2. The native vegetation appears to be established at this area.



## Inspection Photos



**Photo 7.** Facing northeast at the location. The native vegetation appears to be established at this area.



## Inspection Photos



**Photo 8.** There is post and some wire that remain around the location that needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321901 | Date: 4/9/2025

Inspection Photos



**Photo 9.** There is a pipe riser found approximately 500 ft. northwest of this abandoned wellsite.

