

Inspection Photos
Location Name: HSR Miller Federal 15-6A
Location ID: 330898



Photo 1 Location.




Photo 2 Wellhead/BOP



Inspection Photos
Location Name: HSR Miller Federal 15-6A
Location ID: 330898



Photo 3 Circulation tanks & Rig pump.



Photo 4 Ranger WO Rig & Wireline truck.