

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNE

Location ID: 335276

Date: 4/10/2025



Location Overview – Photo #08074




Location Overview – Photo #08077

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNE

Location ID: 335276

Date: 4/10/2025



Location – Photo #08075



Location – Photo #08076

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNE

Location ID: 335276

Date: 4/10/2025



Location – Photo #08082



Location – Photo #08078

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNE

Location ID: 335276

Date: 4/10/2025



Location – Photo #08084



Location – Photo #08083

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNE

Location ID: 335276

Date: 4/10/2025



PRV Terminates in Unsafe Manner – Photo #08079



Open-Ended Line – Photo #08080