


## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Apr 14, 2025 at 12:08:56 PM  
CO



Apr 14, 2025 at 12:11:49 PM  
CO

Photo # 1184 From entrance to location

Photo # 1185 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1186 Location



Photo # 1187 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1188 Location



Photo # 1189 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1190 Location



Photo # 1191 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1192 Tank lacks required labeling



Photo # 1193 Tank lacks required labeling

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1194 Tank lacks required labeling



Photo # 1195 Tank lacks required labeling



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOWNING RWF 22-24 Pad

Location ID: 335511



Photo # 1196 Tank lacks required labeling