

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 04/15/2025 Document Number: 403990905

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 61250 Contact Person: Risa O'Bryhim Company Name: MULL DRILLING COMPANY INC Phone: (316) 264-6366 Address: 1700 N WATERFRONT PKWY B#1200 Fax: () City: WICHITA State: KS Zip: 67206-6637 Email: risa@mullcompanies.com

Identification Information

API Number: 05 - - ECMC Facility ID: 160007 Initial Form 19 or 27 Document number: Facility Name: Quiver Unit Facility Number: Facility Type: UIC Enhanced Recovery Location QtrQtr: S2N2S 2 Section: 1 Township: 17S Range: 48W Meridian: 6 County: KIOWA Field Name: QUIVER Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Mull Drilling Company, Inc. Agent Name: Risa O'Bryhim Title: Sr Compliance Specialist Phone Number: 316-264-6366 Email: risa@mullcompanies.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 160007 Facility Name: Quiver Unit Facility Type: UIC Enhanced Recovery Location: QtrQtr: S2N2S 2 Sec: 1 Twp: 17S Range: 48W Meridian: 6 County Name: KIOWA Latitude: 0.000000 Longitude: 0.000000

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 125977 Document Name: QU #1_20250415 upload File Name: QU #1_20250415 upload.xls SampleType: Matrix: Facility ID: 160007 Sample ID: 666450 Sample Name: QU #1 Sample Date: 06/17/2024 Collection Point: Tank Matrix: WATER Pre Post: 806.b-UIC Periodic Analysis Project Number: 60455187 Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: 6045518700 1

Batch ID: 125977 Document Name: QU #1_20250415 upload File Name: QU #1_20250415 upload.xls

SampleType: _____ Matrix: _____

Facility ID: 160007 Sample ID: 666451 Sample Name: QU #1 Sample Date: 06/17/2024

Collection Point: Tank Matrix: WATER Pre Post: 806.b-UIC Periodic Analysis

Project Number: 60455187 Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Pace Analytical Lab Sample ID: 6045518700
2

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	04/17/2025
Environmental Data	EDD contains duplicate analytes with different result values of benzene, ethylbenzene, M-+P-xylene, o-xylene, naphthalene, toluene, total xylenes, and TVPH - GRO.	03/14/2025
Total: 2 comment(s)		