

Inspection Photos

Location Name: JOHNSON A-66N64W/13SWSE

Location #: 310573



Photo #1

Johnson A 13-23 (123-26611) Wellsite

Temporarily Abandoned | TA

Emergency contact number peeling

OOSLAT tag NOT posted



Photo #2

Johnson A 13-23, Trump A 13-9, 13-10 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Johnson A 13-15

Plugged & Abandoned | PA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: JOHNSON A-66N64W/13SWSE

Location #: 310573




Photo #3

Johnson A 13-23, Trump A 13-9, 13-10 Battery site

Abandoned: ALL Equipment Removed

Wellsite(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources