

Inspection Photos
Location Name: Vicki 21-34
Location ID: 305623



Photo 1 well head and equipment



Photo 2 production equipment and tank battery

Inspection Photos
Location Name: Vicki 21-34
Location ID: 305623



Photo 3 clean up area of stained soil



Photo 4 clean up area of stained soil