

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404150907

Date Received:

04/18/2025

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

-

[rbucogccinspectionreports@chevron.onmicrosoft.com](mailto:rbucogccinspectionreports@chevron.onmicrosoft.com)

White, Jeff

[jeffery.white@chevron.com](mailto:jeffery.white@chevron.com)

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 713900744

Inspection Date: 07/02/2024

FIR Submit Date: 07/03/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**LOCATION - Location ID: 329434**

Location Name: SMITH-64N64W Number: 9SWNW County: \_\_\_\_\_

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.328686 Longitude: -104.562604

**FACILITY - API Number: 05-123-00 Facility ID: 329434**

Facility Name: SMITH-64N64W Number: 9SWNW

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.328686 Longitude: -104.562604

**CORRECTIVE ACTIONS:**

1 CA# 196492

Corrective Action: The Operator has two compliance scenario options, in the case of continued use of the tank battery location the location will be continued to be stabilized and offsite sedimentation will be repaired and reclaimed as soon as environmentally possible based on crop harvest.

Date: \_\_\_\_\_

In the case of decommissioning of the tank battery location the entirety of the disturbance caused by the offsite sedimentation shall be included in Final Reclamation activities.

Response: CA COMPLETED

Date of Completion: 04/02/2025

Operator Comment: Chevron decommissioned the tank battery and performed reclamation activity to stabilize the area. A portion of the remedial activities have been completed after the equipment was removed. Right now the area has been prepped for farming season. We are to return in winter to finish remedial activity at Tank Battery.

ECMC Decision:

ECMC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with stabilizing the footprint of the tank battery caused by the runoff from the overspray by the center pivot across the equipment on the former location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed:

Title: HSE

Date: 4/18/2025 4:35:25 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404150907	FIR RESOLUTION SUBMITTED
404150919	photos

Total Attach: 2 Files