

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2620 From entrance to location



Photo # 2621 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429




Photo # 2622 Location

Photo # 2623 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2624 Location



Photo # 2625 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2626 Location



Photo # 2627 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2628 Location



Photo # 2629 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2630 Location



Photo # 2631 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2632 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 2633 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2634 Open ended load line



Photo # 2635 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2636 Open ended load line



Photo # 2637 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2638 Open ended load line



Photo # 2639 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Apr 17, 2025 at 2:21:30 PM
CO



Apr 17, 2025 at 2:24:50 PM
CO

Photo # 2640 Arctitherm E-50 tank label lacks required information

Photo # 2641 Arctitherm E-50 tank label lacks required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2642 Arctictherm E-50 tank label lacks required information



Photo # 2643 Arctictherm E-50 tank label lacks required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2644 Arctictherm E-50 tank label lacks required information



Photo # 2645 Labeling on methanol tank is weathered & some required information is illegible & additionally tank capacity is incorrect

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429





Photo # 2646 Labeling on methanol tank is weathered & some required information is illegible & additionally tank capacity is incorrect

Photo # 2647 Correct tank capacity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2648 Carport on location/not in compliance with CECMC rules



Photo # 2649 Shed on location/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2650 Unused stainless tubing & hoses



Photo # 2651 Unused equipment & stored supplies

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2652 Unused equipment & stored supplies



Photo # 2653 Unused equipment & stored supplies

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2654 Unused equipment & stored supplies



Photo # 2655 Unused equipment & stored supplies

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2656 Unused hoses, batteries, solar panels & misc



Photo # 2657 Unused batteries

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2658 Unused batteries, hoses, solar panels & misc



Photo # 2659 Unused equipment & stored supplies

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2660 Unused pumps



Photo # 2661 Stored trailers & pressure washer

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2662 Unused chemical tank



Photo # 2663 Unused chemical tank

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2664 Unused chemical tank



Photo # 2665 Unused equipment, stored supplies, trailers, carport, shed & misc

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 17-15 Pad

Location ID: 335429



Photo # 2666 Unused equipment, stored supplies, trailers, carport, shed & misc