

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



Location Overview – Photo #08130



Location – Photo #08149

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



Location – Photo #08133



Location – Photo #08134

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



Location – Photo #08131




Location – Photo #08152

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



**Inaccurate Information on Tank Label – Photo #08140**



**Stored Supplies/Wildlife Entry Hazard – Photo #08144**

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



Apr 16, 2025 at 11:50:07  
530 County Road 335  
New Castle CO 81647  
United States

**Stored Supplies/Wildlife Entry Hazard – Photo #08146**



Apr 16, 2025 at 11:51:05  
530 County Road 335  
New Castle CO 81647  
United States

**Stored Equipment – Photo #08147**

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/C Pad

Location ID: 420223

Date: 4/16/2025



Open-Ended Load Line – Photo #08145