

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**Photos from 4/9/2025**

**Bridge over Porcupine Creek where flowlines are crossing the creek.**



**Photos from 4/9/2025**

**4" flowline open ended and bent. 8" pipe used to sleeve Mustangs flowline to Burns #9-35-6-94W well.**

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**4" flowline open ended and bent. 8" pipe used to sleeve Mustangs flowline to Burns #9-35-6-94W well.**



Photos from 4/9/2025

**4" flowline open ended and bent. 8" pipe used to sleeve Mustangs flowline to Burns #9-35-6-94W well.**

**Flowline runs east up hillside through the clearing.**

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**Photos from 4/16/2025**

**Terra Energy located their lines and marked them with paint and flags.**



**Photos from 4/16/2025**

**Terra Energy located their lines and marked them with paint and flags.**

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**Photos from 4/16/2025  
Bent flowline**



**Photos from 4/16/2025  
Open ended flowline**

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**Photos from 4/16/2025  
Vaquero welded on pipe**



**Photos from 4/16/2025  
Vaquero welded on pipe**

**MUSTANG RESOURCES LLC  
Rulison Flowline System  
Facility Id. # 469336**



**MUSTANG RESOURCES LLC**  
**Rulison Flowline System**  
**Facility Id. # 469336**

