

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Location Overview – Photo #08228



Location – Photo #08229

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Location – Photo #08247



Location – Photo #08230

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Location – Photo #08248



Location – Photo #08246

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Apr 17, 2025 at 12:02:09
530 County Road 335
New Castle CO 81647
United States



Apr 17, 2025 at 11:58:32
530 County Road 335
New Castle CO 81647
United States

Location – Photo #08249

Illegible Tank Label – Photo #08238

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Staining in Tank Containment – Photo #08239

Staining in Tank Containment/Stored Supplies – Photo #08240

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Staining in Tank Containment – Photo #08243



Stored Supplies/Wildlife Entry Hazard – Photo #08244

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/B Pad

Location ID: 416722

Date: 4/17/2025



Stored Supplies/Wildlife Entry Hazard – Photo #08241



Stored Supplies/Wildlife Entry Hazard – Photo #08242