

# Final Reclamation Inspection

April 8, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330075

Inspection Document #: 718800135

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PSC #41-3  
Location ID: 330075



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates the operator has performed final reclamation activities with evidence of drill row seeding, however vegetation does not meet Rule 1004 final reclamation standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: PSC #41-3  
Location ID: 330075



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: PSC #41-3  
Location ID: 330075



**Photo 7.** Photo taken from the access road, facing West. See comments under Photo 1.



**Photo 8.** Photo taken from the access road, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: PSC #41-3  
Location ID: 330075



**Photo 9.** Photo taken of the reference area, north of the location, facing Northwest. Photo illustrates degraded conditions with weedy vegetation (bindweed) and bare ground cover. Prairie dogs have historically inhabited the area and the land appears to have been dryland cropland which has been left unmanaged for the past approximately 20 years.

