



LEASE INSPECTION FORM

Date 3/20/85
 Operator PAINE Field SELOWO CREEK
 Lease Name & No. BOX ELDER FARMS 1 County ADAMS
 Tank Battery No. _____ Location SW SE 6-35-65W
 Legal Description
 Type of Inspection P+A
 Water Inflow _____ (Bbls. per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
 Type of Tank

SKIM TANK _____

PIT NO. 1 _____

PIT NO. 2 _____

PIT NO. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety
 Conditions, Etc.)

SURFACE REHABILITATED INTO FARMLAND, COULD BE
UNDER SOME EARTHWORK FROM NEWLY COMPLETED 6-32 B.E.F.
BY BASS ENTER.

RECOMMENDED ACTION (If Required) NONE, APPEARS P+A PROPERLY

INSPECTOR BSK