

# Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 319319

Well Name: BBR ABBOTT FARMS #22-34

Inspection Document #: 718600501

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BBR ABBOTT FARMS #22-34  
Location ID: 319319



**Photo 1.** Looking east down access road towards the well location from well API #123-10420.



**Photo 2.** Looking west away from the well. T post markers are still in place in approximate flowline path (red circle).





Inspection Photos  
Location Name: BBR ABBOTT FARMS #22-34  
Location ID: 319319



**Photo 3.** Looking north across well location. Location appears unchanged since last inspection. Undesirable weeds such as Kochia and Russian Thistle are present on location.



**Photo 4.** Looking northwest across soil piles near wellhead. Soil is placed on a liner, concrete and trash is present. No perimeter BMPs are present.





Inspection Photos  
Location Name: BBR ABBOTT FARMS #22-34  
Location ID: 319319



**Photo 5.** Looking north across excavation. Fencing is not correctly installed and excavation remains open.



**Photo 6.** Looking east across excavation. See photo 5 comments.

