

Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 464350

Location Name: Lone Eagle/13-34

Inspection Document #: 718600503

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 1. Looking south across the tank battery. Weeds outside secondary containment have been mowed.



Photo 2. Looking south across the west side of the tank battery. Undesirable weeds such as Kochia and Russian Thistle are present inside of secondary containment.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 3. Looking northwest at the east side of the tank battery. Undesirable weeds inside of secondary containment. Unused equipment remains on site.



Photo 4. The eastern tank has an open inspection hatch. Birds were observed entering the hatch at the time of inspection.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 5. Looking south at the separator sheds on the southern side of location. Excavation and soil pile appear unchanged since last reclamation inspection (12/18/2024).



Photo 6. Open excavation remains. Fence is improperly installed. Undesirable weedy vegetation such as Kochia and Russian Thistle is present around the sheds.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 7. Soil pile and stormwater BMPs remain on location.



Photo 8. Inside of southern separator shed. Stained soil remains around separator.

