

Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318979

Location Name: DORIS #12-34

Inspection Document #: 718600505

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 1. Looking west down the access road. Road is rutted resulting in widening of the road.



Photo 2. Looking west down the south side of location. Undesirable weeds such as Kochia and Russian Thistle are present on location.

Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 3. Looking west down the north side of location.



Photo 4. Inside the engine shed. Stained soil is present around the engine. The engine was not running at time of inspection. Engine guard is not installed.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Apr 15, 2025
97° E
ECMC

Photo 5. Chemicals, trash and a bucket of oil is present both in and out of secondary containment.



Apr 15, 2025
297° NW
ECMC

Photo 6. Broken belts left in place around pulley.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 7. Southern side of wellhead. Wellhead does not appear to have active leaks. It appears that some stained soil was removed.



Photo 8. West side of wellhead. See photo 7 comments.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 9. South side of separator at the sank battery. Tank battery location has been mowed. Weeds have been removed from secondary containment. Trash has been removed from around separator.



Photo 10. Looking at the north side of separator. Pipe remains at the separator (red circle).



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 11. Looking at the east side of the tank battery. Weeds have been mowed on location. Bird protectors have not been installed on open pipes.



Photo 12. Looking at the west side of the tank battery. Location has been mowed.