

Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 427114

Location Name: Bosky PC/Z22-14 Tank

Inspection Document #: 718600510

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bosky PC/Z22-14 Tank
Location ID: 427114



Photo 1. Looking north across the tank battery location. Weeds have been controlled around the tank battery and within secondary containment.



Photo 2. Tank battery sign. Weeds have been controlled.



Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 3. Looking north down the east side of the location. Bucket of oil has been removed. Produced water tank without secondary containment remains on location.



Photo 4. Looking at the joint between produced water tank and separator. Does not appear to be leaking. Some soil may have been removed around the joint.



Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 5. Looking south at the separator. Undesirable weeds such as Kochia and Russian Thistle are present behind the produced water tank (red circle).



Photo 6. Deep ruts in the access road to the west of the tank battery.

