

Interim Reclamation and Stormwater Inspection

April 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 427113

Well Name: Bosky PC #Z22-14

Inspection Document #: 718600512

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bosky PC #Z22-14
Location ID: 427113




Photo 1. Looking north across the location. Interim production area has been reduced.



Photo 2. Looking at the east side of the location. Crop growth is patchy within the disturbance area.



Inspection Photos
Location Name: Bosky PC #Z22-14
Location ID: 427113




Photo 3. Looking north from the well location. Crop growth is patchy within the disturbance area.



Photo 4. Unlabeled tank on the east side of the well.



Inspection Photos
Location Name: Bosky PC #Z22-14
Location ID: 427113



Photo 5. Looking south at the wellhead.



Photo 6. Looking at the west side of the location. Some undesirable weeds such as Kochia are present. Well is partially dismantled and equipment remains on location.

