

# Inspection Photos

Loc: 308437

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 4/22/2025

County: LAS ANIMAS



Inspection Photos



**Photo 1.** Facing east along the former access road which remains per approved variance.



Inspection Photos



**Photo 2.** Facing east toward the location which was not recontoured per approved variance.



## Inspection Photos



**Photo 3.** Facing northeast the location.



## Inspection Photos



**Photo 4.** Facing toward the fill slope which is stabilized with perennial vegetation.



## Inspection Photos



**Photo 5.** Facing west along the cut slope which is stabilized with perennial vegetation.



## Inspection Photos



**Photo 6.** Facing east along the cut slope which is stabilized with perennial vegetation.

