

Inspection Photos

Loc: 307743

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/22/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the former access road.



Inspection Photos



Photo 2. Further along the access road facing northeast.



Inspection Photos



Photo 3. Facing northeast along the former road toward the location.



Inspection Photos



Photo 4. Facing northeast toward the location. Perennial vegetation is established throughout the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307743 | Date: 4/22/2025

Inspection Photos



Photo 5. Northeast side of the location facing southwest.



Inspection Photos



Photo 6. Facing toward the fill slope which is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307743 | Date: 4/22/2025