

Inspection Photos

Loc: 308443

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/22/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308443 | Date: 4/22/2025

Inspection Photos



Photo 2. Further along the access road facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308443 | Date: 4/22/2025

Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308443 | Date: 4/22/2025

Inspection Photos



Photo 4. Facing northeast along the cut slope which is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308443 | Date: 4/22/2025

Inspection Photos



Photo 5. There are noxious weeds (Scotch thistle) growing at the top of the cut slope..



Inspection Photos



Photo 6. Northeast side of the location facing southwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308443 | Date: 4/22/2025

Inspection Photos



Photo 7. Facing toward the fill slope which is stabilized with perennial vegetation.

