



WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

Well 99999999  
Operator Snyder  
Location NE NW 4-35-66  
Field \_\_\_\_\_

API Number 05 - 031 - 6528  
Permit # \_\_\_\_\_  
County Denver  
Inspector EBB

AL/PA/DA Inspection Results:

Well Status:

Pass(Y)  Fail(N)  Date 10 8 92 ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_ TA \_\_\_\_\_

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: 10-11-72 Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bond Release OK: Yes  No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

Date of Safety/Status Inspection \_\_\_\_\_

Comments: \_\_\_\_\_



00375091

Violations: Yes \_\_\_\_\_ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_

Had a plug (5 5/8") at  
the surface, type in  
on the intent to abandon  
Jim

ALSO -

Plug - 1550' - 1250'  
1000' - 700'  
450' - 200'

Type on approved copy  
Made phone call to  
Jim Snyder.

Jim

10/4/72