

Inspection Photos

Loc: 308881

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/22/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northeast along the access road which has not been recontoured and reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308881 | Date: 4/22/2025

Inspection Photos



Photo 2. Facing north at the location which was recontoured and reclaimed except for the access road that continues thru the location.



Inspection Photos



Photo 3. Facing northwest at the location.



Inspection Photos



Photo 4. There is some noxious weed (Field bindweed) emerging adjacent to the road that will need to be controlled.



Inspection Photos



Photo 5. There is some noxious weed (Field bindweed) emerging adjacent to the road that will need to be controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308881 | Date: 4/22/2025

Inspection Photos



Photo 6. North side of the location facing south. The access road remains through the center of the location.



Inspection Photos



Photo 7. East side of the location facing southwest.

