

Inspection Photos

Loc: 308422

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/22/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308422 | Date: 4/22/2025

Inspection Photos



Photo 2. Facing northeast at the location. Sign is posted at the meter shed.



Inspection Photos



Photo 3. Facing toward the PW pit.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308422 | Date: 4/22/2025