

Inspection Photos
Location Name: Pagel 33-34 4N47W
API Number: 125-09241



1. Lease sign at well location.



2. View of wellhead.


Inspection Photos

Location Name: Pagel 33-34 4N47W

API Number: 125-09241



3. Well location overview.



4. Lease sign at gathering location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pagel 33-34 4N47W
API Number: 125-09241



5. Broken meter shed door handle. Door is jammed shut.



6. Gathering location overview.