

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 1 –Well placard

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 3 – Valve

Photo 4 – Impacted soils

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 5 – Spill Path

Photo 6 – Drainage, end of spill path