

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Location Overview – Photo #08322



Location – Photo #08332

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Location – Photo #08336



Location – Photo #08333

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Illegible Wellhead Sign – Photo #08323

Illegible Wellhead Sign – Photo #08324

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Illegible Wellhead Sign – Photo #08325

Illegible Wellhead Sign – Photo #08326

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Illegible Wellhead Sign – Photo #08327


Illegible Wellhead Sign – Photo #08329

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Illegible Wellhead Sign – Photo #08330



Stored Equipment – Photo #08328

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692

Location ID: 418772

Date: 4/22/2025



Stored Supplies/Wildlife Entry Hazard – Photo #08339



Stored Supplies/Wildlife Entry Hazard – Photo #08340