

Inspection Photos

Location Name: LAPP-66N64W/13SWSW

Location #: 309285



Photo #1

Lapp 13-33 (123-25429) Wellsite

Temporarily Abandoned | TA

Weed housekeeping needed



Photo #2

Lapp 13-31, 13-33, 13-35 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Lapp 13-24, 13-32, 13-34, Lapp A 24-30D

Plugged & Abandoned | PA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: LAPP-66N64W/13SWSW

Location #: 309285



Photo #3

Lapp 13-31, 13-33, 13-35 Battery site

Abandoned: ALL Equipment Removed

Well(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources