

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott/21A-36-692

Location ID: 335153

Date: 4/23/2025



Apr 23, 2025 at 12:13:06
6051 Divide Creek Rd
Silt CO 81647
United States

Location Overview – Photo #08370



Apr 23, 2025 at 12:14:31
6051 Divide Creek Rd
Silt CO 81647
United States

Location – Photo #08371

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott/21A-36-692

Location ID: 335153

Date: 4/23/2025



Location – Photo #08372




Location – Photo #08374

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott/21A-36-692

Location ID: 335153

Date: 4/23/2025



Location – Photo #08375



Location – Photo #08377

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott/21A-36-692

Location ID: 335153

Date: 4/23/2025



Location – Photo #08376



Debris – Photo #08373

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott/21A-36-692

Location ID: 335153

Date: 4/23/2025



PRV Terminates in Unsafe Manner – Photo #08384