

Final Reclamation and Stormwater Inspection

Date: 04/17/2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 389727

Inspection Document #: 718700333

Logan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Emerald Unit 1-35
Location ID: 389727



Photos 1 & 2. Apparent stained soils and road base material observed around the former well location.

Inspection Photos
Location Name: Emerald Unit 1-35
Location ID: 389727



Photos 3 & 4. Additional reclamation activities are required as the former well location has evidence of contour/grading issues and the presence of road base material.

Inspection Photos
Location Name: Emerald Unit 1-35
Location ID: 389727



Photos 5 & 6. Additional reclamation activities are required as the former well location has evidence of contour/grading issues and the presence of road base material.

Inspection Photos
Location Name: Emerald Unit 1-35
Location ID: 389727



Photo 7. A subsidence (approximated by red outline) observed west of the former well location.