



WELL SITE INSPECTION FORM



WELL NAME Box Elder Farms 11-24 API NUMBER 05 - 001 - 08871
 OPERATOR Ampet PERMIT NUMBER 88-721
 LOCATION SE SW 11-35-65W COUNTY Adams
 FIELD Mamella INSPECTOR Briley

AL/PA/DA INSPECTION RESULTS: WELL STATUS:
 PASS(Y) FAIL(N) ✓ DATE 9-9-88 FN FD WO

=====

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE DEPTH SET CMT VOL WOC
 CONSISTENT WITH APD CASING PROGRAM? RETURNS
 RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET? COMPLETION RIG/ACTIVITY
 DRILLING PITS: CLOSED OPEN ✓ WELLHEAD SYSTEM INSTALLED
 TANK ID: YES NO NA WELL SIGN: YES NO
 SKIM PIT: gal TANKS: () bbls
 EQUIPMENT
 BRADENHEAD PRESSURE FLUID: NO YES TYPE
 METER RUN: YES NO WELL STATUS: PR TA SI WELL CAT 3-

AL/PA/DA INSPECTION

DATE PLUGGED: 7-22-88 DATE PERMIT EXPIRED:
 HOLE PLUGGED: YES ✓ NO PITS BACKFILLED: YES NO ✓
 MATERIAL BURIED: YES ✓ NO NA SITE CLEAN: YES ✓ NO
 BOND RELEASE OK: YES NO ✓ FED HOLE MARKER: YES NO ✓

DATE OF SAFETY/STATUS INSPECTION 9-9-88

COMMENTS Pit has water. Near marsh area
Cover before winter. Mud tanks dry.
