

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 1 – Signs at Entrance

Photo 2 – Wellheads

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 3 – 14-21-16XRLNC Wellhead Sign

Photo 4 – E-A-21-HNB Wellhead

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 5 – Trash around Wellheads

Photo 4 – Trash at Wellheads

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 7 – Trash around Wellheads



Photo 8 – Separators

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 9 – North Separator – Open to Atmosphere

Photo 10 – Separators

Inspection Photos  
Location Name: Antelope 14-21 PAD  
Location ID: 441376



Photo 11 – Maintenance Tank



Photo 12 – Gas Lift Injection Meter Shed