

Operator: BONANZA CREEK ENERGY OPERATING CO.

Location Name: ANTELOPE M-31

Loc ID: 428278

Inspection: 718700266



Exhibit A



Exhibit B

CA: This location does not comply with Rule 1004. During this inspection, it was observed that the location appears to have been contoured and graded to reflect adjacent topography. The former tank battery and well locations consist primarily of unstabilized/bare soils and debris from undesirable vegetation (russian thistle/tumbleweeds). A Colorado List C Noxious Weed (cheatgrass) was also observed to be growing throughout the disturbance areas and will require management. Additional reclamation activities are required to comply with Rule 1004. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has addressed the vegetation issue in order to comply with Rule 1004. This location has been inter-seeded. Additional crimped straw mulch was decided against in order to minimize disturbance to new seedlings and existing perennial grasses that were observed