

Inspection Photos

04/16/2025

Operator: QB ENERGY OPERATING LLC
#10844

Location ID: 414152

Inspection Doc: 718100500

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location south, southwest, northwest to northeast. Location has been reduced to areas reasonably needed for production; vegetation appears to be progressing towards 1003 Standards. Photos also show perimeter fence; maintenance advised.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 2: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 3: Photos taken from the west end of the Location. Photos examples showing outlet at the sediment trap has not been maintained in proper functioning condition; erosion degradation evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 4: Photo taken from the interim areas of the Location. Photo example of Noxious Weed Rosettes observed within the interim.

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 5: Operator information at signage incorrect.

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 414152



Photo 6: Photo taken from the west end of the tank battery Location, facing east. Photo shows stabilization and tracking controls show sign of disrepair; degradation/rutting observed.