

Final Reclamation and Stormwater Inspection

April 29, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 459452

Well Name: Kallsen 24-9 #1, Madison 23-9/

Inspection Document #: 718600537

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kallsen 24-9 #1, Madison 23-9/
Location ID: 459452



Photo 1. Looking west across the tank battery location. On the east side of the location there is a large bare patch near the road (red circle).



Photo 2. Looking west across the location on the north side. It appears there is some desirable vegetation establishment. Some portions of the location have lower vegetation establishment (red circle).



Inspection Photos
Location Name: Kallsen 24-9 #1, Madison 23-9/
Location ID: 459452



Photo 3. Meter shed remains on location.



Photo 4. Looking east across the location. Undesirable weed Russian Thistle is present on location. The west side of the location appears to have lower vegetation establishment.

