

# Inspection Photos

API: 071-06191

Operator: OGRIS OPERATING LLC

Inspection Date: 4/29/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources


Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



## Inspection Photos



**Photo 2.** Facing toward the east side of the location.



## Inspection Photos



**Photo 3.** There is a dripping water leak at the wellhead and the grate does not fully cover the well cellar.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06191 | Date: 4/29/2025