

Inspection Photos

ID: 453009

Operator: OGRIS OPERATING LLC

Inspection Date: 4/29/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the compressor facility.



Inspection Photos



Photo 2. Oil stained soils need to be cleaned up and properly disposed..



Inspection Photos



Photo 3. Facing toward the produced water tank. It appears fluids leaked out the top running down the side.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 453009 | Date: 4/29/2025