

# Inspection Photos

API: 071-07182

Operator: OGRIS OPERATING LLC

Inspection Date: 4/29/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the wellsite.



## Inspection Photos



**Photo 2.** There is oily fluids in the engine skid.



## Inspection Photos



**Photo 3.** There is a dripping water leak at the wellhead. Stained soils need to be cleaned up.



## Inspection Photos



**Photo 4.** Facing northeast overlooking the location.

