


Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Apr 28, 2025 at 4:16:26 PM
CO



Apr 28, 2025 at 4:18:02 PM
CO

Photo # 6920 From entrance to location

Photo # 6921 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 6922 Location



Photo # 6923 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 6924 Location



Photo # 6925 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 6926 Location



Photo # 6927 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Apr 28, 2025 at 4:19:28 PM
CO

Photo # 6928 Hole in liner/liner needs maintenance



Apr 28, 2025 at 4:19:59 PM
CO

Photo # 6929 Hole in liner/liner needs maintenance