

# Inspection Photos

API: 071-06343

Operator: OGRIS OPERATING LLC

Inspection Date: 4/29/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the wellsite. Sign has fallen over and the electric utility line has not been removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06343 | Date: 4/29/2025



## Inspection Photos



**Photo 2.** Facing west at the abandoned wellsite. This area of the former road needs to be reseeded. There is mostly weeds (Kochia) growing in the area between the two blue lines.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06343 | Date: 4/29/2025



## Inspection Photos



**Photo 3.** The area of the former well has not established perennial vegetation.



## Inspection Photos



**Photo 4.** The electric line dead ends at this location and needs to be removed back to the next active wellsite that it serves.

