



WELL SITE INSPECTION FORM

LOCATION SESE 10-33-65W FIELD MANDELLA
OPERATOR BASS ENTERPRISES COUNTY ADAMS
WELL NAME BASS-BOX ELDER FARMS PERMIT # 10-33

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____ DEPTH: _____

BOP'S _____ RETURNS: _____ WOC: _____

CONTACT _____ CMT VOL: _____

ADEQUATE AQUIFER PROTECTION? _____

COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES ___ NO ___ PRODUCTION STRING: _____

WATER DISPOSAL: PITS ___, INJECTED ___, COMMERCIAL ___, UNKNOWN ___, N.A. ___

PITS: PERMIT Y ___ N ___, SKIM TANK Y ___ N ___, DIMENSIONS _____

LEASE SIGN: YES ___ NO ___ TANK ID: YES ___ NO ___ NA ___ FENCED: YES ___ NO ___

SURFACE EQUIPMENT: _____

COMMENTS: _____

DATE OF P&A INSPECTION 10/8/86

PITS BACKFILLED: YES ___ NO SURFACE RECLAIMED: YES NO ___

HOLE MARKER: YES ___ NO SITE CLEAN: YES NO ___

BOND RELEASE OK: YES NO ___ LANDOWNER RELEASE: YES ___ NO ___

COMMENTS: WHEAT FIELD STUBBLE

DATE OF SAFETY INSPECTION _____

COMMENTS: _____

INSPECTOR JSK

API No. 05-001-0 ?

P&A Inspected: Yes No ___