



00417856

LEASE INSPECTION FORM

Date 3/20/85  
 Operator BASS ENT. Field MANDELLA  
 Lease Name & No. BOX ELDER FMS 10-33 County ADAMS  
 Tank Battery No. \_\_\_\_\_ Location SESE 10-35-65W  
 Legal Description  
 Type of Inspection PIA  
 Water Inflow \_\_\_\_\_ (Bbls. per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of Tank

SKIM TANK 15 X 60 X 10, PLASTIC LINER, OPEN, DRY

PIT NO. 1 60 X 100 X 5, UNLINED, DRY, DRILLING MUD RESERVE PIT

PIT NO. 2 10 X 20 X 8, TRASH, DRY, OPEN, UNLINED

PIT NO. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

NO EVIDENCE TO INDICATE WELL WAS NOT PIA PROPERLY. RIF  
PAD EVIDENT & LOCATION OF HOLE EVIDENT, BUT NO PIPE VISIBLE.

RECOMMENDED ACTION (If Required) CALL "GEORGES PUMPING SERVICE" +  
ASK WHEN EARTHWORK FOR RESTORATION WILL BEGIN, CHECK WELL FILE FOR  
PIA DATE

INSPECTOR JSK

