

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



Photo # 6742 From entrance to location




Photo # 6743 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



Photo # 6744 Location



Photo # 6745 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



Apr 28, 2025 at 2:48:03 PM  
CO



Apr 28, 2025 at 2:53:34 PM  
CO

Photo # 6746 Location

Photo # 6747 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



**Photo # 6748 Stored cars, truck, trailer, tires & keg in the interim area**



**Photo # 6749 Stored cars & truck in the interim area**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



Photo # 6750 Stored cars & truck in the interim area



Photo # 6751 Stored cars, truck & trailer in the interim area

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRASS MESA RANCH 33-1 (A33NW) Pad

Location #: 323850



Photo # 6752 Stored cars & trailer in the interim area



Photo # 6753 Stored cars, truck & trailer in the interim area