

Inspection Photos

April 28th, 2025

Operator: Hilcorp Energy Company - 10133

Location ID: 325961

Inspection Document #: 714002113

La Plata County, CO

Township: SWNW 20 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

April 28, 2025
243° SW



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961

April 28, 2025
358° N

April 28, 2025
79° E

Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: project area is dominated by Field Bindweed with minimal establishment of desirable species observed. Additional seeding/reclamation efforts are needed.



Photo 4. Patches of Field Bindweed observed throughout the project area.

Inspection Photos
Location Name: Allison Unit 116
Location ID: 325961

April 28, 2025
251° W

April 28, 2025
72° E



Photo 5. Perimeter fencing remains on location.

April 28, 2025
344° N

